



PUBLIC WORKS REPORT August 2025

WATER: In the month of August 2025, the water system met the standards and rules of TCEQ. The Public Works crew has continued to focus on marking water and sewer lines throughout the town. We have repaired many water leaks caused by the fiber optics crews. Services lines that connect homes to our water mains have been a common problem. We have been able to continue to utilize the contractor's equipment to be able to make repairs in house, as they have happened. Outside of the water leaks caused by the contractors, regular repairs have been made to leaks that have occurred in our system. A repair to the water main had to be made on the 100 block of Hollow Dr. The town's water supply continues to be adequate for the demand placed on the system.


WORK ORDERS:

Miscellaneous	0	Meter Accuracy	0
Water Quality	0	Low Pressure	
Meter Swap	0	Leak	4
Occupant Change	9	Information	1
Repair	30	Disconnect	7
Connect	1	Cut off	0
ReInstate	5	Meter read	0
		TOTAL	57

Automated Meter Leak Notifications

78

Ryan Berry, Water/Wastewater Superintendent

Dated: 

9/17/25



PUBLIC WORKS WASTEWATER REPORT

August 2025

In the month of August, the wastewater plant and system remained in compliance with TCEQ standards and regulations. The wastewater plant is operating normally. Public works has continued to mark the collection system as fiber optic crews are still working throughout our town. This month we have had to make repairs to several repairs to sewer taps that the fiber optics crews have damaged. The lift station on Augusta experienced pump failure and a bypass pump needed to be rented to maintain the collection system. The pump in the lift station was inspected prior to failure and determined that a new pump needed to be bought to replace it. The approval for the pump was authorized on July 17, 2025, by the city council.


The issues with the lift station carried on into September. The bypass pump rented maintained the collection system for about a week before the rented pump failed. A new pump was rented and delivered; however this pump was not in good working order and failed within a couple of days of installation. This caused an overflow of a manhole on Split Rail golf course. Magnaflo was contracted to pump the lift station as well as clean up the overflow. The site was washed, vacuumed and disinfected using HTH. Magnaflo was contracted to pump the collection system out, daily, until a pump can be placed into the lift station to restore normal operation.

Repairs to wastewater system:

Sewer Taps repaired on Deer Creek, Pepperbush, and Silver Ridge.

Gallons pumped to Split Rail:

2.0 MGD

A handwritten signature in black ink, appearing to be 'B. B. Jones', written over a horizontal line.

Water/Water SuperIntendent