



PUBLIC WORKS REPORT April 2026

WATER:

In the month of April, the water system operated in accordance with TECQ regulations. The first quarter DLQR, has been submitted to TCEQ. Watts Drilling completed the well rehab at water plant 4. The results of the rehab have doubled the production of the well. The well was producing a maximum of 20 gpm. After the rehab the well is producing 40 gpm. A storm on April 25, caused a power outage, that affected some of the control components for the scada system that affected water plant 4 and water plant 5. Scada control was lost at these plants. The parts were ordered and installed on April 29, and normal scada control was restored.

WORK ORDERS

Miscellaneous	4	Meter Accuracy	0
Water Quality	0	Low Pressure	0
Meter Swap	0	Leak	0
Occupant Change	3	Information	0
Repair	40	Disconnect	0
Connect	2	Cut off	2
Reinstate	1	Meter read	1
		TOTAL	56

Automated Meter Leak Notifications	62
---	----

Ryan Berry Water/Wastewater Superintendent -----



PUBLIC WORKS WASTEWATER REPORT

April 2026

In the month of April, the wastewater plant maintained TCEQ standards. One of the effluent pumps, that pumps treated water to Split Rail Golf Course, failed. The other remaining pump continues to be in working condition. A new pump was ordered and installed. Currently both effluent pumps are in working condition. Due to heavy spring rainfall, a supplement was purchased, and regiment was started to help combat the rapid changes in the plant's biology, that can accompany an uptick in flow. This treatment is like a probiotic and vitamin for the bacteria that treats the water.

Repairs to wastewater system:

Effluent pump bought and Installed

Gallons pumped to Split Rail:

.887 MG

Water/Water Superintendent